WESTON Ref. No.

01-0025

MCP INTERIM PHASE II REPORT AND CURRENT ASSESSMENT SUMMARY FOR EAST STREET AREA 1/USEPA AREA 3



VOLUME III OF IV

GENERAL ELECTRIC COMPANY PITTSFIELD, MASSACHUSETTS

OCTOBER 1994

BLASLAND, BOUCK & LEE, 'NC. 6723 TOWPATH ROAD, BOX 66 SYRACUSE, NEW YORK 13214

MCP INTERIM PHASE II REPORT AND CURRENT ASSESSMENT SUMMARY FOR EAST STREET AREA 1/USEPA AREA 3

TABLE OF CONTENTS

VOLUME III OF IV

APPENDICES

Appendix J MCP Analytical Data Sheets

Section 1 - Volatile Organics - Soil Section 2 - Semivolatile Organics - Soil Section 3 - Pesticides/PCBs - Soil

Section 4 - PCBs - Soil

Section 5 - Organophosphorus Pesticides - Soil

Section 6 - Herbicides - Soil

Section 7 - Polychlorinated Dibenzo ins/furans - Soil

Section 8 - Metals - Soil Section 9 - Cyanide - Soil Section 10 - Phenols - Soil Section 11 - Sulfide - Soil

Section 12 - Volatile Organics - Groundwater

Section 13 - Semivolatile Organics - Groundwater

Section 14 - Pesticides/PCBs - Groundwater

Section 15 - Organophosphorus Pesticides - Groundwater

Section 16 - Herbicides - Groundwater

Section 17 - Polychlorinated Dibenzodioxins/furans - Groundwater

Section 18 - Metals - Groundwater Section 19 - Cyanide - Groundwater Section 20 - Phenols - Groundwater Section 21 - Sulfide - Groundwater

REPORT

219 CH-0005 22.19 01-0025

MCP INTERIM PHASE II REPORT AND CURRENT ASSESSMENT SUMMARY FOR EAST STREET AREA 1/USEPA AREA 3

VOLUME IV OF IV

General Electric Company
Pittsfield, Massachusetts

October 1994

BLASLAND, BOUCK & LEE, INC.
ENGINEERS 6 SCIENTISTS

MCP INTERIM PHASE II REPORT AND CURRENT ASSESSMENT SUMMARY FOR EAST STREET AREA 1/USEPA AREA 3

VOLUME IV OF IV

GENERAL ELECTRIC COMPANY PITTSFIELD, MASSACHUSETTS

OCTOBER 1994

BLASLAND, BOUCK & LEE, INC. 6723 TOWPATH ROAD, BOX 66 SYRACUSE, NEW YORK 13214

MCP INTERIM PHASE II REPORT AND CURRENT ASSESSMENT SUMMARY FOR EAST STREET AREA 1/USEPA AREA 3

TABLE OF CONTENTS

VOLUME IV OF IV

APPENDICES

2/10/04

Appendix K MCP Slug Test Results
Appendix L Information Related to Miscellaneous Soils and Other Investigations

Section 1 - Excavations Near Building 9B Section 2 - Excavations Near Building 10

Section 3 - Excavations Within/Near Building 14
Section 4 - Excavations Near Building 100
Section 5 - Storm Sewer Sediment

Section 6 - Southside Recovery System Excavations

Section 7 - Sweeper Soils

Appendix M USEPA Report on Residential Air Monitoring in Lakewood Area